

Residential Basement Walls: Problems and Solutions

Daniel R. Eimer¹, E.I.T., and D. Bell², S.E.

Abstract:

This paper outlines problems observed in residential basement walls constructed with concrete masonry units (CMU) resisting lateral earth pressure. A rational, idealized analysis of a discrete block wall structure follows, attempting to define the structural mechanism of cracked walls, including a limit or failure condition. The resulting conclusion presents an engineered reinforcement solution simple in theory and practical in economy and installation.

To purchase full article: Please use this direct link to purchase the TMS Journal Volume of this article, Volume 8, Issue 1: <https://masonrysociety.org/product/tms-ejournal-vol-8-no-1/>

Otherwise, consider becoming a TMS member for full access to all TMS Journal articles: <https://masonrysociety.org/membership/#join>

DOI: 10.70803/001c.140530

¹ Chief Design Engineer/Structural, Randolph & Associates, Inc., Peoria, IL.

² Manager, Structural Engineering, Randolph & Associates, Inc., Peoria, IL.